MSDS MATERIAL SAFETY DATA SHEET

RUPERT, GIBBON & SPIDER PO BOX 425, HEALDSBURG CA, 95448 TEL: (707) 433-9577 FAX: (707) 433-4906

Castaway

MSDS No: #2900 **Date:** 09/21/10

1. Product Identification

Product Name: Castaway Stamp Pad
Product Code: #330

2. Hazardous Ingredients

Hazardous Components: Ammonia 3%, Urea 5%, Water 70%

3. Physical Data

Boiling Point: 104 C
Vapor Pressure: N/A
Vapor Density: N/A
Solubility in Water: Soluble
Appearance: Clear liquid
Specific Gravity: 1.33 g/cm3
Melting Point: -10 C
pH: 10-11
Density: 1.33 g/cm3

4. Fire and Explosive Data

Flash Point: >100 C
Extinguishing Media: Water fog, CO2, foam or dry chemical
Special Fire Fighting Procedures/Unusual Fire or Explosive Hazards: Use self-contained breathing apparatus and protective gear

5. Reactivity Data

Stability: Stable
Incompatibility (materials to avoid): None Known
Hazardous Decomposition Products: Acidic solutions cause decomposition
Polymerization: Will not occur

6. Health Effects Data

Routes of Entry: N/A
Acute: N/A
Chronic: N/A
Carcinogenic: N/A
Signs & Symptoms of Exposure: Contact with the eyes and skin may result in irritation. Inhalation of the vapors or mists may result in respiratory irritation. Ingestion of the liquid may result in gastric disturbances.
Medical Conditions Aggravated by Exposure: N/A

7. Emergency and First Aid Procedures

Eye Contact: immediately flush with water for 15 minutes. If irritation develops consult a physician.
Skin Contact: Wash affected areas with soap and water. Remove and launder contaminated clothing before reuse. If irritation develops consult a physician.

Ingestion: if swallowed, dilute with water and immediately induce vomiting. Never give fluids or induce vomiting if the victim is unconscious or having convulsions. Get immediate medical attention.
Inhalation: Move to fresh air. Aid in breathing, if necessary and get medical attention.

8. Employee Protection Recommendations

Respiratory Protection: if vapors or mists are generated, wear a NIOSH approved organic vapor/mist respirator
Ventilation: Use local exhaust
Protective Gloves: Rubber or Vinyl gloves
Eye Protection: Chemical goggles
Other Protection: Coveralls, apron, boots as necessary to prevent skin contact
Storage & Handling: Protect from freezing

9. Spill or Leak Procedures

In Case Material is Released/Spilled: Spills should be contained, solidified and placed in suitable containers for disposal in a licensed facility. This material is not regulated under RCRA or CERCLA.
Waste Disposal Method: Incinerate or bury in a licensed facility in accordance with all Federal, state and local regulations. Do not discharge into waterways or sewer systems without proper authority

Notice to Reader

The information contained in this MSDS is based on data from sources considered to be reliable but Rupert, Gibbon & Spider Inc. does not guarantee the accuracy or completeness thereof. Rupert, Gibbon & Spider Inc. urges each customer or recipient of this MSDS to study it carefully to become aware of and understand the hazards associated with this product. The reader should consider consulting reference works or individuals who are experts in ventilation, toxicology or fire and understand the data in this MSDS.